



Read all about it...

Toro Downhole Tools drills over 65,000 hours with an average Mean Time Between Failures (MTBF) of 3,500 hours!!

Setting an Industry Standard...

Toro drills over 65,000 hours with an average MTBF of 3500

Special points of interest:

- **2008-2011 65,000 + hours drilled.**
- **2008-2011 Mean Time Between Hours (MTBF) average of 3500 hours.**
- **2010 Mean Time Between Assembly errors (MTBA) over 25,000 hours.**

With three years under their belt, Toro Downhole Tools is setting industry standards with their fleet of high performance downhole drilling motors.

In 2008 Toro drilled 14,240 hours delivering a Mean Time Between Failures of 3,570 hours.

In 2009, Toro drilled 15,023 hours delivering a Mean Time Between Failures of 3,653 hours.

In 2010, Toro drilled 25,397 hours delivering a Mean Time Between Failures of 4,831 hours.

To date, Toro has drilled just over 12K' in 2011 setting the pace to exceed 2010 performance by 15%.

Total hours drilled in the short three (3+) years totals over 65,000 with an average Mean Time Between Failures of 3500 hours.

With 2011 just getting it's feet wet, Toro looks to continue their growth and success with the introduction of their Shock Sub fleet and their new products, the Motor Optimizer and Drilling Jars.

In addition, Toro will look to gain some additional market share with diversification and bundled services teaming with some of the industry's leading downhole service companies.

By joining resources and assets, Toro looks to push on the competition forcing notification and acknowledged respect that this small company is not just another fly by night operations and will be in the industry for the long term.



Over 2.6 million feet drilled!!

Toro Service Facility delivers a Mean Time Between Assembly (MTBA) errors of over 25,000 hours!

In 2010, the Toro Downhole Tools Service Facility set an astonishing record of over 25,000 hours without an assembly error (MTBA). The Service Facility's success is contributed to the high quality Motor Technicians and their every day positive

attitude to do the job right the first time and no shortcuts to quality.

Toro's new 22,500' Service Facility located in Tomball, Texas offers improved turnaround times and room for growth.

For more information about Toro, please visit the web site at www.torotools.com.

